

SECRET

OUT52056

SECRET 142107Z

1963 OCT 15 02 05Z

25X1

1. CAMERA B 7 WAS USED IN MISSION 3747 FLOWN ON 11 OCTOBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

15 OCT 1963

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINUS DENSITY DOTS 1.55" APART AND 0.5" FROM THE INBOARD EDGE ARE PRESENT THROUGHOUT THE MISSION PARALLEL TO THE MAJOR AXIS OF THE FILM. WATER MARKS FROM 1.0" TO 3.0" WIDE AND TRANSVERSE ACROSS THE FORMAT ARE PRESENT ON FRAMES 296 TO 298. THERE IS INTERMITTENT INBOARD AND OUTBOARD EDGE STATIC THROUGHOUT THE MISSION.

HFS H
CJS S

C. 9L SIDE: A BAR-TYPE LIGHT LEAK EXTENDS TRANSVERSELY ACROSS FRAME 002. MINUS DENSITY DOTS 1.55" APART AND PARALLEL TO THE MAJOR AXIS OCCUR 1.85" FROM THE OUTBOARD EDGE OF THE FILM THROUGHOUT THIS SIDE.

G (File)

D. BOTH SIDES: MINOR PINHOLES, SCRATCHES, AND ABRASIONS OCCUR INFREQUENTLY THROUGHOUT THE MISSION. THERE ARE ALSO MINOR INTERMITTENT PROCESSING STREAKS AND/OR SCRATCHES PRESENT IN THIS MISSION. THE LAST TITLED FRAME ON EACH SIDE WAS 2044.

1

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

Declassification Review by
NGA/DoD

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING OF THE POSITIVE IS GOOD.

C. CLOUDS OR HAZE DEGRADED OR OBSCURED 20 PERCENT OF THE MISSION.

SECRET

25X1

END OF MESSAGE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification